	100. 3 3 3 7 3 6 0 13 7 3		
	and the state of t		
	470		
4.4	MALFUNCTION REP		SENT 08/1548Z.
	SINGLE SPEED SHUTTER		the second secon
FOR MSN 3229	9. THERE WAS NO REQ	UIREMENT TO	O USE TWO SPEED SHUTTER
		200 (黄夜)就了加州。	CIFIED FAST SHUTTER SPE
			D FAST POSITION OF THE
AND F-10 APE	ERTURE. THE NORMAL		
AND F-10 APE SPEED SHUTTE	ERTURE. THE NORMAL : ER ARE IDENTICAL.	SHUTTER AND	D FAST POSITION OF TO
AND F-10 APE SPEED SHUTTE 3. THERE	ERTURE. THE NORMAL : ER ARE IDENTICAL. E IS NO REASON WHY	SHUTTER AND	CANNOT BE USED ON
AND F-10 APE SPEED SHUTTE 3. THERE	ERTURE. THE NORMAL : ER ARE IDENTICAL.	SHUTTER AND	CANNOT BE USED ON
AND F-10 APE SPEED SHUTTE 3. THERE NEXT SORTIE	ERTURE. THE NORMAL : ER ARE IDENTICAL. E IS NO REASON WHY	SHUTTER AND	CANNOT BE USED ON
AND F-10 APE SPEED SHUTTE 3. THERE NEXT SORTIE USING TWO SE	ERTURE. THE NORMAL : ER ARE IDENTICAL. E IS NO REASON WHY WITH SO-130 FILM HOW PEED SHUTTER.	SHUTTER AND	CANNOT BE USED ON
AND F-10 APE SPEED SHUTTE 3. THERE NEXT SORTIE USING TWO SE 4. RECOM	ERTURE. THE NORMAL ER ARE IDENTICAL. E IS NO REASON WHY WITH SO-130 FILM HOW PEED SHUTTER. MMEND USE OF SN 118,	SHUTTER AND	CANNOT BE USED ON EE NO ADVANTAGE IN
AND F-10 APE SPEED SHUTTE 3. THERE NEXT SORTIE USING TWO SE 4. RECOM	ERTURE. THE NORMAL ER ARE IDENTICAL. E IS NO REASON WHY WITH SO-130 FILM HOW PEED SHUTTER. MMEND USE OF SN 118, TOT AND F-10 APERTUR	SHUTTER AND	CANNOT BE USED ON EE NO ADVANTAGE IN
AND F-10 APE SPEED SHUTTE 3. THERE NEXT SORTIE USING TWO SE 4. RECOM	ERTURE. THE NORMAL ER ARE IDENTICAL. E IS NO REASON WHY WITH SO-130 FILM HOW PEED SHUTTER. MMEND USE OF SN 118, TOT AND F-10 APERTUR	SHUTTER AND	CANNOT BE USED ON EE NO ADVANTAGE IN
AND F-10 APE SPEED SHUTTE 3. THERE NEXT SORTIE USING TWO SE 4. RECOM	ERTURE. THE NORMAL ER ARE IDENTICAL. E IS NO REASON WHY WITH SO-130 FILM HOW PEED SHUTTER. MMEND USE OF SN 118, TOT AND F-10 APERTUR R E T	SHUTTER AND WEVER WE SE	CANNOT BE USED ON EE NO ADVANTAGE IN

T O P S E C R E T 081932Z 25X1 IMMEDIATE CITE 25X1 25X1 REF 4471 25X1 FYI ESTIMATE FOOTAGE OF 25X1 SHUTTER OPERATING WAS LESS THAN 100 FT. THE 80 FT REPORTED IN 25X1 THE OF WHICH NEGLIBLE AMOUNT EXPOSED IN 25X1 TGT AREA. TRANSPORT DID NOT PLAY A PART IN THE CONFIG MALFUNCTION. PLS ADVISE IF YOU DESIRE IMMEDIATE SHIPMENT OF 3229 TAKE WITH ROUTE OVERLED'S IAW REF. C-130 WILL BE RETAMAN 25X1 PHFING YOUR REPLY. TOPSECRET 25X1 CFN 0148 X 4471 FY1 CONF IG 3229 C-130

Sanitized Copy Approved for Release 2009/10/29: CIA-RDP89B00569R000700110007-9